



ROTARY SWITCH WIRING



POTS WIRING



$$R^* = R5, R6, R7, R8, R9, R10$$